


Three-phase Electric Motors wound for 230/400V 50Hz can be supplied from 230V 50Hz single-phase supply. The motor needs to be connected in DELTA for 230V.



## KOSTAL INVEOR M

Motor Integrated Inverters

